

M&M Engineering's Boiler Tube Failure Handbook



Deformation—Thinning



Locations	Superheater, Reheater
Boiler Type	Power
Industry	Electric Utility

Appearance	Smooth surface
Mechanism	Fly Ash Erosion
Comments	Wall thinning leads to stress rupture failure

