

M&M Engineering's Boiler Tube Failure Handbook



Hole—Waterside



Locations	Waterwall, Superheater, Reheater
Boiler Type	Power
Industry	Electric Utility

Appearance	ID pitting with corrosion tubercles
Mechanism	Oxygen Pitting
Comments	Improper lay-up, poor control of oxygen on startup

