

M&M Engineering's Boiler Tube Failure Handbook



Hole—Material Defect



Locations	Superheater
Boiler Type	Power
Industry	Pulp and Paper

Appearance	Porosity in weld
Mechanism	Weld Defect
Comments	Weld porosity may be due to inadequate shield gas flow or contamination on the surface of the material.

