

M&M Engineering's Boiler Tube Failure Handbook



Crack—Not in or near weld—Longitudinal



Locations	Waterwall
Boiler Type	Power
Industry	Electric Utility

Appearance	Fishmouth Opening
Mechanism	Hot Tensile Overload
Comments	Usually caused by starvation or severe wall loss due to erosion or oxidation.

