

# M&M Engineering's Boiler Tube Failure Handbook



Crack—In or near weld or attachment—Transverse



Locations	Superheater
Boiler Type	Power
Industry	Electric Utility

Appearance	Complete failure at weld
Mechanism	Thermal Fatigue, DMW Creep
Comments	Failure of Pressure Induction Weld

