

M&M Engineering's Boiler Tube Failure Handbook



Hole—Fireside



Locations	Waterwall
Boiler Type	Reformer
Industry	Petrochem

Appearance	Metal wastage
Mechanism	Fireside Corrosion
Comments	Corrosion often due to sulfur in the fuel creating acidic deposits.

